

STEULERFLAKE SPG

Airless-spray applied lining with barrier fillers; High chemical and thermal resistance

Base

Epoxy Novolac Vinyl ester resin

Material Group

Tank- / vessel linings – Flake coatings

Description

Glass flake filled system based on special vinyl ester resin with excellent resistance against high temperatures and aggressive chemicals. Thanks to the high content of plate-like barrier filling materials that are aligned parallel to the surface, excellent diffusion / permeation resistant, also toward water vapour is achieved.

Furthermore, the system avails good mechanical resistance and wear resistance.

Nominal thickness is 1.2 mm.

Use

Lining for ducts and tanks and chimneys of raw gas cleaning plants and other equipment based on steel structures in several industries.

Properties

- high chemical resistance
- high diffusion resistance
- thermal resistance up to 200 °C (dry exposure), up to 80 °C (wet exposure)
- standard thickness approx. 1.2 mm

Physical Data

Property (unit), Test method	Value
Density (g/cm ³), DIN EN ISO 1183-1, ASTM D 792	1.3
Flexural strength (MPa), DIN EN ISO 178, ASTM C 580	60
Compressive strength (MPa), DIN EN ISO 604, ASTM C 579	80
The thermal coefficient of linear expansion (1/K), ISO 11359-2, ASTM C 531	2.2 x 10 ⁻⁵
Tensile Strength (MPa), DIN EN ISO 527, ASTM C 307	40

Chemical Resistance

Extensive resistance to acids (also concentrated sulfuric acid), alkalis, solvents, oils and other, also oxidizing chemicals.

Please contact our application engineering for approval of the project-specific possible application.

Substrate

Steel

Refer to DIN EN14879-1 as well as to STEULER-KCH-Formblatt 020.

The steel surface shall be sandblasted to a metallic bright finish. A preparation degree of SA 2 ½ as specified in DIN EN ISO 12944-4 and a roughness grade “medium (G)” as specified in DIN EN ISO 8503-1 must be achieved; minimum surface roughness $R_z = 70 \mu\text{m}$. After blasting, the formation of new rust must be prevented by suitable measures, e.g. immediate application of a primer.

The substrate should have a temperature of approx. 12 – 25 °C.

Moisture

During application, the substrate must be kept absolutely dry. Uncured material has to be protected from any kind of moisture (condensation, fog, precipitation or other water source). Distance to dew point has to be at least 3 K, at a relative humidity of above 70 % at least 5 K.

System Design

- Steulerflake Primer HT
- Steulerflake SPG

Packaging / Shelf life

All components must be stored and transported dry and frost-free. Shelf life is specified for a storage temperature of 20 °C. Higher temperatures reduce, lower temperatures increase the shelf life.

Components	Colour approx.	Item number	Package	Content	Shelf life
Steulerflake-Priming-Solution HT		5032063001	Hobbock	25 kg	3 Months
Steulerflake SPG		5032065001	Hobbock	25 kg	3 Months
Oxydur-Hardener C		5032015007	Bottle	1 kg	12 Months
Steulerflake-Colour-Paste blue	Blue	5011015007	Bucket	1 kg	12 months
Steulerflake-Colour-Paste blue	Blue	5011015003	Bucket	5 kg	12 months

Mixing Ratio / Consumption

Steulerflake Primer HT

	Part by weight	Part by volume
Steulerflake-Priming-Solution HT	1.000	0.900
Oxydur-Hardener C	0.020	0.020
Consumption	approx. 0.150 kg / m ²	
Work steps	1	

Steulerflake SPG

	Part by weight	Part by volume
Steulerflake SPG	1.000	0.830
Oxydur-Hardener C	0.020	0.020
Steulerflake-Colour-Paste blue	0.005	0.003
Consumption per application	approx. 0.700 kg / m ²	
Layer thickness by 3 applications	1.2 mm	
Work steps	minimum 2	

Waiting Times

Waiting times between the layers depend on the temperature and are as follows:

10 °C	minimum 8 h	maximum 120 h
20 °C	minimum 6 h	maximum 78 h
30 °C	minimum 4 h	maximum 24 h

Pot Life

The working times depend on the temperature and are as follows:

Temperature	Primer	Cover Layers
10 °C	approx. 70 minutes	approx. 90 minutes
20 °C	approx. 45 minutes	approx. 60 minutes
25 °C	approx. 30 minutes	approx. 40 minutes

Curing times

To achieve full mechanical resistance 3 days and chemical resistance 7 days.

Safety measures

Mix and apply material only in well ventilated areas. Provide ventilation suited to the conditions when working in pits or tanks. Do not smoke!

Do not expose materials to heat or open flame. This applies in particular to welding works (weld beads). Avoid direct skin contact with the materials. Wash hands with soap and water; do not clean the skin with solvents. Use barrier soap and protective creams on exposed skin areas. In all other respects comply with the relevant regulations for prevention of accidents.

Refer to the Safety Data Sheets!

GISCODE

Product	GISCODE
Steulerflake Primer HT	SB-STY 10
Steulerflake SPG	SB-STY 10

Cleaning of Equipment

Tools soiled with uncured materials can be cleaned with STEULER UNIVERSAL CLEANER (Technical Information TI 190). Only clean in well ventilated areas.

Steulerflake-Cleaner A to clean the spray equipment.

All information contained in this Technical Information is based on the present state of our knowledge and practical experience. All data are approximate values for guidance only. A legally binding warranty of certain characteristics or the suitability for a certain purpose of use cannot be derived from this.

The information given in this Technical Information is our intellectual property. The Technical Information may neither be copied nor used by unauthorized parties, nor professionally distributed or otherwise made accessible to third parties without our prior consent.

This issue replaces all previous versions.